

Facility Summary in MUSSELSHELL County in the City of MELSTONE

Location: JAKES GARAGE
221 US HIGHWAY 12
MELSTONE, MT 59054 MUSSELSHELL

Sys Fac ID: 33-01481

Last Inspected On: 12/22/2015

Operating Permit Renewal Date: 3/30/2019

Contact: Jake Zaharko, (406) 358-2389

Owners/Operators: Jakes Garage Inc, Owner (406)-358-2389 221 US HIGHWAY 12
MELSTONE MT 59054
Tim DeJaegher, UST Class A Operator
Larry Zaharko, UST Class A Operator
Tim DeJaegher, UST Class B Operator
Larry Zaharko, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	17	12/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
3770			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		1/4/2013	Manual Interstitial Monitor	Deferred	
3,750					
9	17	12/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
3771			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		1/4/2013	Manual Interstitial Monitor	Deferred	
2,250					

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Location: WELLS FARGO BANK ROUNDUP
12 MAIN ST
ROUNDUP, MT 59072 MUSSELSHELL

Sys Fac ID: 33-02079
Last Inspected On: 7/31/2013
Operating Permit Renewal Date: 12/28/2016

Contact: Joe Eckhardt, (406) 323-2000

Owners/Operators: Wells Fargo Bank Roundup, Owner (406)-323-2000 12 MAIN ST
ROUNDUP MT 59072-2828
Chris Anderson, UST Class A Operator
Chris Anderson, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	10/6/1993	Cathodically Protected Steel	Copper	Flapper Valve (Auto Shutoff)
3495		7/31/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Safe Suction	Galvanic
Heating Oil		7/31/2013	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
2,000			Other , Other		

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Location: CONOCO CONVENIENCE CENTER
806 MAIN ST
ROUNDUP, MT 59072 MUSSELSHELL
Contact: Terry Watkins, (406) 323-1108

Sys Fac ID: 33-05030
Last Inspected On: 9/6/2013
Operating Permit Renewal Date: 12/14/2016

Owners/Operators: McCleary Distributing Inc, Owner (406)-323-1108 PO BOX 406
ROUNDUP MT 59072-0406
Terry Watkins, UST Class A Operator
Terry Watkins, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	19	10/1/1996	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1594		10/9/2012	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		11/9/2011	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000		11/9/2011			
2	26	8/30/1989	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1592			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		11/9/2011	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		8/16/2013			
3	23	9/1/1992	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1593			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		11/9/2011	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		8/16/2013			
4	26	8/30/1989	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1591			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		11/9/2011	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		8/16/2013			

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Location: CONOCO CONVENIENCE CENTER
806 MAIN ST
ROUNDUP, MT 59072 MUSSELSHELL

Sys Fac ID: 33-05030
Last Inspected On: 9/6/2013
Operating Permit Renewal Date: 12/14/2016

Contact: Terry Watkins, (406) 323-1108

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	19	10/1/1996	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1595		10/9/2012	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		11/9/2011	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
2,000		9/7/2010			
11	19	10/1/1996	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1596		10/9/2012	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		11/9/2011	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000		9/7/2010			
12	19	10/1/1996	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1597		10/9/2012	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		11/9/2011	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
2,000		9/7/2010			

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Location: EXPRESS CENTER CONVENIENCE STORE
701 1ST AVE W
ROUNDUP, MT 59072 MUSSELSHELL

Sys Fac ID: 33-06612

Last Inspected On: 12/17/2014

Operating Permit Renewal Date: 2/7/2018

Contact: Rachel McCord, (406) 323-3443

Owners/Operators: Stockton Oil Company, Owner (406)-245-6376 PO BOX 1756
BILLINGS MT 59103-1756

Mykel Stockton, UST Class A Operator
Christopher Stockton, UST Class B Global Operator
Joseph Stockton, UST Class B Global Operator
Mykel Stockton, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	30	3/26/1985	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
3757			Lined Interior/Impressed Current	None	Yes
Temporarily Out of Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		12/17/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation	Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation, MLLD Line Tightness Testing	
10,000		8/29/2011	TLS-350/Gilbarco EMC , Veeder Root		
2	30	3/26/1985	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
3758			Lined Interior/Impressed Current	None	Yes
Temporarily Out of Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		12/17/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation	Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation, MLLD Line Tightness Testing	
8,000			TLS-350/Gilbarco EMC , Veeder Root		
3	30	3/26/1985	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
3759			Lined Interior/Impressed Current	None	Yes
Temporarily Out of Use			Electronic Line Leak Detector	Pressurized	Impressed Current, Not Applicable
Gasoline		12/17/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation	Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation, MLLD Line Tightness Testing	
4,000		7/15/2011	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Location: EXPRESS CENTER CONVENIENCE STORE
701 1ST AVE W
ROUNDUP, MT 59072 MUSSELSHELL

Sys Fac ID: 33-06612

Last Inspected On: 12/17/2014

Operating Permit Renewal Date: 2/7/2018

Contact: Rachel McCord, (406) 323-3443

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	17	10/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1985			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Diesel		12/12/2011	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, Stat. Inventory Reconciliation	Continuous Interstitial Monitor, Stat. Inventory Reconciliation	
8,000			Gilbarco EMC Basic , Gilbarco		
5	17	10/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1986			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Diesel		12/12/2011	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, Stat. Inventory Reconciliation	Continuous Interstitial Monitor, Stat. Inventory Reconciliation	
5,000			TLS-350/Gilbarco EMC , Veeder Root		
6	17	10/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1987			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable, Not Applicable
Diesel		12/12/2011	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, Stat. Inventory Reconciliation	Continuous Interstitial Monitor, Stat. Inventory Reconciliation	
4,000			TLS-350/Gilbarco EMC , Veeder Root		